

SB0087S01 compared with SB0087

~~text~~ shows text that was in SB0087 but was deleted in SB0087S01.

Inserted text shows text that was not in SB0087 but was inserted into SB0087S01.

DISCLAIMER: This document is provided to assist you in your comparison of the two bills. Sometimes this automated comparison will NOT be completely accurate. Therefore, you need to read the actual bills. This automatically generated document could contain inaccuracies caused by: limitations of the compare program; bad input data; or other causes.

Representative Daniel McCay proposes the following substitute bill:

SCHOOL SECURITY LOCKS

2018 GENERAL SESSION

STATE OF UTAH

Chief Sponsor: Todd Weiler

House Sponsor: ~~_____~~ Daniel McCay

LONG TITLE

General Description:

This bill amends provisions of the State Construction and Fire Codes Act.

Highlighted Provisions:

This bill:

- ▶ amends the International Building Code and International Fire Code regarding:
 - hardware height on a door for certain occupancies ~~in~~ for purposes of a lockdown or ~~during~~ a lockdown drill; and
 - door operations provisions for locks and bolt locks, and latching and unlatching, for certain occupancies ~~in~~ for purposes of a lockdown or ~~during~~ a lockdown drill ~~;~~ and
- ▶ makes technical changes.

Money Appropriated in this Bill:

SB0087S01 compared with SB0087

None

Other Special Clauses:

None

Utah Code Sections Affected:

AMENDS:

15A-3-105, as last amended by Laws of Utah 2016, Chapter 249

15A-5-205, as last amended by Laws of Utah 2016, Chapter 216

Be it enacted by the Legislature of the state of Utah:

Section 1. Section **15A-3-105** is amended to read:

15A-3-105. Amendments to Chapters 10 through 12 of IBC.

(1) In IBC, Section 1010.1.9, an exception is added as follows: "Exception: Group E occupancies ~~{in}~~for purposes of a lockdown or ~~{during}~~ a lockdown drill in accordance with Section 1010.1.9.5 Exception 5."

(2) In IBC, Section 1010.1.9.2, "Exception:" is deleted and replaced with "Exceptions: 1."

(3) In IBC, Section 1010.1.9.2, a new Exception 2 is added as follows: "2. Group E occupancies ~~{in}~~for purposes of a lockdown or ~~{during}~~ a lockdown drill may have one lock below 34 inches in accordance with Section 1010.1.9.5 Exception 5."

(4) In IBC, Section 1010.1.9.3, a new number 6 is added as follows: "6. Group E occupancies ~~{in}~~for purposes of a lockdown or ~~{during}~~ a lockdown drill in accordance with Section 1010.1.9.5 Exception 5."

(5) In IBC, Section 1010.1.9.4, a new exception 6 is added as follows: "6. Group E occupancies ~~{in}~~for purposes of a lockdown or ~~{during}~~ a lockdown drill in accordance with Section 1010.1.9.5 Exception 5."

(6) In IBC, Section 1010.1.9.5, a new exception 5 is added as follows: "5. Group E occupancies may have a second lock on classrooms ~~{when all}~~for purposes of ~~{the following exist}~~a lockdown or lockdown drill, if:

5.1 The application of the lock is approved by the ~~{State Fire Marshal}~~code official.

5.2 The unlatching of any door or leaf does not require more than two operations.

5.3 The lock can be released from the opposite side of the door on which it is installed.

SB0087S01 compared with SB0087

5.4 The lock is only applied during lockdown or during a lockdown drill.

5.5 The lock complies with all other state and federal regulations, including the Americans with Disabilities Act of 1990, 42 U.S.C. Sec. 12101 et seq."

~~(7)~~ (7) In IBC, Section 1010.1.9.6, a new number 9 is added as follows: " 9. The secure area or unit with special egress locks shall be located at the level of exit discharge in Type V construction."

~~(8)~~ (8) In IBC, Section 1011.5.2, exception 3 is deleted and replaced with the following: " 3. In Group R-3 occupancies, within dwelling units in Group R-2 occupancies, and in Group U occupancies that are accessory to a Group R-3 occupancy, or accessory to individual dwelling units in Group R-2 occupancies, the maximum riser height shall be 8 inches (203 mm) and the minimum tread depth shall be 9 inches (229 mm). The minimum winder tread depth at the walk line shall be 10 inches (254 mm), and the minimum winder tread depth shall be 6 inches (152 mm). A nosing not less than 0.75 inch (19.1 mm) but not more than 1.25 inches (32 mm) shall be provided on stairways with solid risers where the tread depth is less than 10 inches (254 mm)."

~~(9)~~ (9) In IBC, Section 1011.11, a new exception 5 is added as follows: " 5. In occupancies in Group R-3, as applicable in Section 101.2 and in occupancies in Group U, which are accessory to an occupancy in Group R-3, as applicable in Section 101.2, handrails shall be provided on at least one side of stairways consisting of four or more risers."

~~(10)~~ (10) In IBC, Section 1013.5, the words ", including when the building may not be fully occupied" are added at the end of the sentence.

~~(11)~~ (11) IBC, Section 1025, is deleted.

~~(12)~~ (12) In IBC, Section 1029.14, exception 2 is deleted.

~~(13)~~ (13) In IBC, Section 1109.8, the following words "shall be capable of operation without a key and" are inserted in the second sentence between the words "lift" and "shall".

~~(14)~~ (14) In IBC, Section 1208.4, subparagraph 1 is deleted and replaced with the following: "1. The unit shall have a living room of not less than 165 square feet (15.3 m²) of floor area. An additional 100 square feet (9.3 m²) of floor area shall be provided for each occupant of such unit in excess of two."

Section 2. Section **15A-5-205** is amended to read:

15A-5-205. Amendments and additions to IFC related to means of egress and

SB0087S01 compared with SB0087

special processes and uses.

(1) In IFC, Chapter 10, Section 1008.2.1, Illumination level under normal power, delete exemption.

(2) In IFC, Chapter 10, Section 1010.1.9, Door operations, a new exception is added as follows: "Exception: Group E occupancies ~~fin~~ for purposes of a lockdown or ~~during~~ a lockdown drill in accordance with Section 1010.1.9.5 Exception 5."

(3) In IFC, Chapter 10, Section 1010.1.9.2, Hardware height, "Exception:" is deleted and replaced with "Exceptions: 1."

(4) In IFC, Chapter 10, Section 1010.1.9.2, Hardware height, Exception 2 is added as follows: "2. Group E occupancies ~~fin~~ for purposes of a lockdown or ~~during~~ a lockdown drill may have one lock below 34 inches in accordance with Section 1010.1.9.5 Exception 5."

(5) In IFC, Chapter 10, Section 1010.1.9.3, Locks and latches, Item 6 is added after the existing Item 5 as follows: "6. Group E occupancies ~~fin~~ for purposes of a lockdown or ~~during~~ a lockdown drill in accordance with Section 1010.1.9.5 Exception 5."

(6) In IFC, Chapter 10, Section 1010.1.9.4, Bolt locks, Exception 6 is added after the existing Exception 5 as follows: "6. Group E occupancies ~~fin~~ for purposes of a lockdown or ~~during~~ a lockdown drill in accordance with Section 1010.1.9.5 Exception 5."

(7) In IFC, Chapter 10, Section 1010.1.9.5, Unlatching, Exception 5 is added after the existing Exception 4 as follows: "5. Group E occupancies may have a second lock on classrooms ~~when all~~ for purposes of ~~the following exist~~ a lockdown or lockdown drill, if:

5.1 The application of the lock is approved by the ~~State Fire Marshal~~ code official.

5.2 The unlatching of any door or leaf does not require more than two operations.

5.3 The lock can be released from the opposite side of the door on which it is installed.

5.4 The lock is only applied during lockdown or during a lockdown drill. ~~fin~~

5.5 The lock complies with all other state and federal regulations, including the Americans with Disabilities Act of 1990, 42 U.S.C. Sec. 12101 et seq."

~~(2)~~ (8) IFC, Chapter 10, Section 1010.1.9.6, Controlled egress doors in groups I-1 and I-2, after existing Item 8 add Item 9 as follows: " 9. The secure area or unit with special egress locks shall be located at the level of exit discharge in Type V construction."

~~(3)~~ (9) In IFC, Chapter 10, Section 1010.1.9.7, Delayed egress locks, Item 9 is added after the existing Item 8 as follows: " 9. The secure area or unit with delayed egress locks shall

SB0087S01 compared with SB0087

be located at the level of exit discharge in Type V construction."

~~[(4)]~~ (10) In IFC, Chapter 10, Section [BE] 1011.5.2, Riser height and tread depth, Exception 3 is deleted and replaced with the following: " 3. In Group R-3 occupancies, within dwelling units in Group R-2 occupancies, and in Group U occupancies that are accessory to a Group R-3 occupancy, or accessory to individual dwelling units in Group R-2 occupancies, the maximum riser height shall be 8 inches (203 mm) and the minimum tread depth shall be 9 inches (229 mm). The minimum winder tread depth at the walk line shall be 10 inches (254 mm), and the minimum winder tread depth shall be 6 inches (152 mm). A nosing not less than 0.75 inch (19.1 mm) but not more than 1.25 inches (32 mm) shall be provided on stairways with solid risers where the tread depth is less than 10 inches (254 mm)."

~~[(5)]~~ (11) IFC, Chapter 10, Section [BE] 1011.11, Handrails, is amended to add the following exception: " 5. In occupancies in Group R-3, as applicable in Section 1014 and in occupancies in Group U, which are accessory to an occupancy in Group R-3, as applicable in Section 1014, handrails shall be provided on at least one side of stairways consisting of four or more risers."

~~[(6)]~~ (12) IFC, Chapter 10, Section 1013.5, Internally illuminated exit signs, delete and rewrite the last sentence to read "Exit signs shall be illuminated at all times, including when the building is not fully occupied."

~~[(7)]~~ (13) IFC, Chapter 10, Section 1025, Luminous Egress Path Markings, is deleted.

~~[(8)]~~ (14) IFC, Chapter 10, Section 1029.14, Seat stability, delete Exemption 2 and renumber exemptions.

~~[(9)]~~ (15) IFC, Chapter 10, Section 1031.2.1, Security Devices and Egress Locks, is amended to add the following: On line three, after the word "fire", add the words "and building."

†

Legislative Review Note

Office of Legislative Research and General Counsel