

H.B. 310

CONSTRUCTION CODE AMENDMENTS

Representative **Larry B. Wiley** proposes the following amendments:

1. *Page 2, Lines 41 through 43:*

- 41 15A-3-307, as enacted by Laws of Utah 2011, Chapter 14
42 { ~~15A-3-308, as enacted by Laws of Utah 2011, Chapter 14~~ }
43 15A-3-309, as enacted by Laws of Utah 2011, Chapter 14

2. *Page 77, Line 1835 through Page 78, Line 1857:*

- 1835 { ~~Section 22. Section 15A-3-308 is amended to read:~~
1836 ~~15A-3-308. Amendments to Chapter 8 of IPC.~~
1837 ~~[IPC, Chapter 8, is not amended.]~~
1838 ~~(1) In IPC, Section 802.1.8, the words "or directly connect" are added after the word~~
1839 ~~"break".~~
1840 ~~(2) In IPC, Section 802, a new Section 802.1.8.1 is added as follows: "802.1.8.1~~
1841 ~~Gravity grease interceptor connection: Those sinks or appliances draining into a gravity grease~~
1842 ~~interceptor shall discharge directly or indirectly through an air gap or air break into a floor~~
1843 ~~sink."~~
1844 ~~(3) In IPC, Section 802, a new Section 802.1.8.2 is added as follows: "802.1.8.2~~
1845 ~~Hydromechanical grease interceptor connection. Those sinks used for washing and primary~~
1846 ~~rinsing of utensils, dishes, pots, pans or service ware and draining through a hydromechanical~~
1847 ~~interceptor shall be directly connected to the interceptor. The sinks shall be trapped and vented~~
1848 ~~to prevent odors from the grease interceptor escaping through the sinks into the building. A~~
1849 ~~flow control device furnished by the manufacturer shall be installed on the inlet side of the~~
1850 ~~interceptor and in accordance with the manufacturers installation instructions. A floor sink~~
1851 ~~shall be installed within five (5') feet downstream of the interceptor outlet. A dedicated branch~~
1852 ~~drain shall be provided to serve the hydromechanical interceptor and the floor sink only. No~~
1853 ~~connections of any kind shall be permitted between the outlet of the interceptor and the~~
1854 ~~connection of the floor sink."~~
1855 ~~(4) In IPC, Section 802, a new Section 802.1.9 is added as follows: "802.1.9 Sanitizing~~
1856 ~~sinks. Sinks used for the sanitizing of utensils, dishes, pots, pans, or service ware shall~~
1857 ~~discharge indirectly through an air gap or air break to the drainage system."~~

-}