


University of Utah Rice Eccles Stadium South End Zone




Existing Clark Building

- Opened in 1982
- Only portion of stadium not upgraded for 2002 Olympics
- Inadequate seating
- Poor/inadequate facilities for home and away teams and referees
- Building systems are failing
- Corroded piping is largely inaccessible within concrete masonry unit (CMU) walls




Proposed Replacement



- Scope determined through extensive survey and market analysis
- 104,000 sf covered; 70,000 sf uncovered
- Increase seating to 51,444
- New locker rooms, training and equipment rooms
- Recruiting, band & press space
- New Premium seating options
- Replace bench seating
- Added concessions and restrooms for all attendees
- Continuous concourse around stadium



New Seating Options




Cost and Financing


Estimated Cost: \$80 million

Financing: Revenue Bond

O&M: Auxiliary Revenues



**Anticipated Sources for
Debt Repayment**



Questions?

